

AASENAA WEATHERS

AIR CONDITIONING & REFRIGERATION COMPANY

Contact: +91 9870300199 / +919819914162 Email: aasenaaweathers@gmail.com Website: www.aasenaaweathers.com

Branded spare parts will be charged at MRP Overall labour cost will not exceed ₹ 500
 The spare parts prices are not fixed it changes according to the on-going market rate
 NOTE: Final Repair cost is provided after inspection of Appliances

Installation	Rate
1.0 Ton Window AC Installation	₹ 799
1.5 Ton Window AC Installation	₹ 899
2.0 Ton Window AC Installation	₹ 999
1.0 Ton Split AC Installation	₹ 1299
1.5 Ton Split AC Installation	₹ 1399
2.0 Ton Split AC Installation	₹ 1499
Uninstallation	Rate
1.0 Ton Window AC uninstallation	₹ 299
1.5 Ton Window AC uninstallation	₹ 399
2.0 Ton Window AC uninstallation	₹ 499
1.0 Ton Split AC uninstallation	₹ 549
1.5 Ton Split AC uninstallation	₹ 649
2.0 Ton Split AC uninstallation	₹ 749
Indoor Split AC Reinstallation	₹ 699
Outdoor Split AC Reinstallation	₹ 799

<u>Extra installation Materials</u>	<u>Rate</u>
1 Meter Copper pipe (with Insulation or wire)	₹ 850
1 Meter Drain pipe (with Insulation)	₹ 100
Split AC Wall Stand	₹ 750
Floor Stand	₹ 750
Universal back plate	₹ 300
Fastener complete set	₹ 200
Making Hole in Brick Wall (7inch to 10inch)	₹ 449
Core Cutting Wall (7inch to 10inch)	₹ 1199
Core Cutting Wall (10inch to 20inch)	₹ 1899
<u>Air Condition Service</u>	<u>Rate</u>
Dry Service Window AC (With Blower)	₹ 299
Dry Service Split AC (With Blower)	₹ 399
Service Window AC (With Jet Pump)	₹ 449
Service Split AC (With Jet Pump)	₹ 549
Deeply Service Window AC (With Jet Pump)	₹ 549
Deeply Service Split AC (With Jet Pump)	₹ 649
Anti-rust Services Window/Split	₹ 945 ₹1145
<u>AC Pump down Service</u>	<u>Rate</u>
Breakdown Split AC Service (At Home & Office)	₹ 1199
Breakdown Split AC Service (At Workshop)	₹ 1799
<u>AC Repair & Maintenance</u>	<u>Rate</u>

AASENAA WEATHERS RATE CARD

AC Repair Start @		₹ 299
1 ton Replacement Compressor		₹ 4000
1.5 ton Replacement Compressor		₹ 4500
2.0 ton Replacement Compressor		₹ 5000
0.8 to 1.0 ton Compressor		₹ 6500
1.5 ton Compressor		₹ 7500
2.0 ton Compressor		₹ 9200
Copper Cooling & Condenser Coil (Window AC)		₹ 4500
Copper Cooling Coil (split AC)		₹ 6000
1.0 ton Copper Condenser Coil (split AC)		₹ 3500
1.5 ton Copper Condenser Coil (split AC)		₹ 4000
2.0 ton Copper Condenser Coil (split AC)		₹ 4500
Expansion Valve Replaced		₹ 1200
Service Valve Replaced (1Pc)		₹ 400
Capillary and Filter Replaced		₹ 350
Flair Nut Replaced		₹ 150
Cooling & Condenser Coil Repair	Labour Charge	₹ 500
U Band Replaced (1pc)		₹ 50
Pin Valve For Window AC		₹ 50
Dead Nut (1pc)		₹ 50
Fan Motor Window AC	₹445 Labour include	₹ 1800
Fan Motor Split AC	₹445 Labour include	₹ 2600
Blower Motor Split AC	₹445 Labour include	₹ 2200
Blower Replaced	₹445 Labour include	₹ 1100
AC Fan Bl		
Replace Flap/Swing motor	₹445 Labour include	₹ 400
Motor Bearing Change		₹ 1000
Noise AC Repair	₹445 Labour Only	₹ 0000
Non Inverter PCB Repaired		₹ 1500
Inverter PCB Repaired		₹ 3999
Replace LVT	₹445 Labour include	₹ 900

AASENAA WEATHERS RATE CARD

Capacitor 2-5 mfd	₹445 Labour include	₹ 250
Capacitor 10-25 mfd	₹445 Labour include	₹ 400
Capacitor 35-50 mfd	₹445 Labour include	₹ 400
Capacitor 50-60 mfd	₹445 Labour include	₹ 400
Replace Sensor	₹445 Labour include	₹ 350
Contactora Replaced	₹445 Labour include	₹ 500
Contactora Daikin/General	₹445 Labour include	₹ 1499
Convert PCB With Remote		₹ 1499
		₹ 1499
Gas Top Up / Gas Filling		Rate
Window AC Gas Top Up		₹ 1100
Split AC Gas Top Up		₹ 1299
1.0 ton Window AC Full Gas Filling		₹ 2399
1.5 ton Window AC Full Gas Filling		₹ 2599
2.0 ton Window AC Full Gas Filling		₹ 2899
1.0 ton Split AC Full Gas Filling		₹ 2299
1.5 ton Split AC Full Gas Filling		₹ 2399
2.0 ton Split AC Full Gas Filling		₹ 2499
Grill Cover	₹445 Labour include	₹ 1499
Water tray	₹199 Labour include	₹ 499
Swing Blade Replaced	₹345 Labour include	₹ 400
Universal Remote		₹ 800
Compressor Grommets Set		₹ 299
Rubber Washer (1pc)		₹ 50
Insulation Sleeves (Per Peace)		₹ 50
Stabilizer Repair		₹ 1499
Water Leakage Repaired Split AC	₹345 Labour	₹ 100
Adjust Grill locks		₹ 345 Labour
Adjust Pipe Tight Compressor Screw		₹ 345 Labour
Connector Wire Replaced	₹345 Labour	₹ 100

AASENAA WEATHERS RATE CARD

Tighten Replaced Thimble	₹345 Labour	₹ 50
External Dust Stick Removal		₹ 345 Labour
Insulation Re fix		₹ 345 Labour
Drain Pipe Adjust		₹ 345 Labour
Noise Adjustment In Motor		₹ 345 Labour
Noise Adjustment In Blower		₹ 345 Labour
Noise Adjustment In Cabinet		₹ 345 Labour
Noise Adjustment In Swing Flap		₹ 345 Labour
Water Leakage In Window AC		₹ 445 Labour

AASENAA

WEATHERS

AIR CONDITIONING & REFRIGERATION COMPANY