

AASENAA WEATHERS

AIR CONDITIONING & REFRIGERATION COMPANY

Contact: +91 9870300199 / Whatsapp: +91 9322001199 Email: aasenaaweathers@gmail.com Website: www.aasenaaweathers.com

Shahabuddin Khan +91 9870300199

Branded spare parts will be charged at MRP Overall labour cost will not exceed ₹ 500

The spare parts prices are not fixed it changes according to the on-going market rate

NOTE: Final Repair cost is provided after inspection of Appliances **Include Labour Charge ₹299**

SEMI WASHING MACHINE Power Unit	Rate
Replace PCB	₹ 1500
Repair PCB	₹ 1000
New PCB	₹ 1500
Re Wiring	₹ 645
SEMI WASHING MACHINE Wash Issue	Rate
Gear Box + Pulley	₹ 1500
Wash Motor	₹ 1750
Timer Wash - Electro Mechanical	₹ 999
Wash Timer	₹ 975
Heater	₹ 799
Spin Wash Capacitor	₹ 480
Thermostat	₹ 399
V Belt	₹ 345
Over Flow Pipe	₹ 210
Motor Pulley	₹ 549
SEMI WASHING MACHINE Spin Issue	Rate

AASENAA WEATHERS AIR CONDITIONING & REFRIGERATION COMPANY

AASENAA WEATHERS (Washing Machine) RATE CARD

Spin motor	₹ 1580
Timer spin	₹ 630
Brake wheel coupler	₹ 599
Brake plate	₹ 349
Brake wire	₹ 199
Assembly shocker	₹ 445
Lid switch	₹ 199
Lid spring	₹ 149
Drain strip	₹ 199
Drain selector	₹ 149
Brake shoe	₹ 249
Coupler bush	₹ 149
SEMI WASHING MACHINE Accessories	Rate
Outer body cabinet	₹ 2499
Inner body plastic tube	₹ 2299
Outer body	₹ 1999
Panel top cover	₹ 999
Wash lid	₹ 799
Spin lid	₹ 699
Spin tub	₹ 899
Washing machine cover	₹ 499
Spin cap	₹ 199
Drain pipe	₹ 205
Power plug 3 pin top	₹ 199
OTP	₹ 349
Stand trolley	₹ 899
Pulsator snap	₹ 199
Pulsator with snap	₹ 899
Descaling powder	₹ 139
Rat mesh	₹ 299
Back cover	₹ 499
Panel top cover	₹ 999
Power cord	₹ 349

AASENAA WEATHERS (Washing Machine) RATE CARD

Drain selector	₹ 99
Lint magic filter	₹ 249
Knob	₹ 149
Spin lid switch	₹ 249
Inlet pipe	₹ 199
Drain strip	₹ 199
Harness of wiring repair	₹ 179
SEMI WASHING MACHINE Water Leakage	Rate
<small>AIR CONDITIONING & REFRIGERATION COMPANY AIR CONDITIONING & REFRIGERATION COMPANY</small>	
Drain case cleaning	₹ 499
Drain valve assembly	₹ 449
Spin tube bellow	₹ 349
Drain bellow	₹ 250
Drain valve spring	₹ 49
SEMI WASHING MACHINE Minor Repair ₹ 299	Rate
<small>AIR CONDITIONING & REFRIGERATION COMPANY AIR CONDITIONING & REFRIGERATION COMPANY</small>	
Electrical plug adjustment	
Wire re taping	
Machine level adjustment	
Belt adjustment	
Cloth coin stuck	
Detergent drawer adjustment	
Drain pipe adjustment	
Filter cleaning	
Tap adapter fixing	
TOP LOAD WASHING MACHINE Power unit	Rate
<small>AIR CONDITIONING & REFRIGERATION COMPANY AIR CONDITIONING & REFRIGERATION COMPANY</small>	
Inverter PCB Repair Top load	₹ 2199
Repair PCB	₹ 1665
LVT	₹ 649
Re wiring (wire crack or burn)	₹ 649

AASENAA WEATHERS (Washing Machine) RATE CARD

New Replace display PCB	₹ 299 Labour
Replace new PCB	₹ 299 Labour
TOP LOAD WASHING MACHINE Wash issue	Rate
Direct drive motor	₹ 3990
Main motor	₹ 1975
DC inlet valve 2 way	₹ 1425
DC inlet valve ¾ way	₹ 1999
AC inlet valve 2way	₹ 965
DC inlet valve 1way	₹ 995
AC inlet valve 1 way	₹ 699
AC inlet valve ¾ way	₹ 1399
Capacitor	₹ 475
V belt	₹ 299
Wash timer	₹ 749
Heater sensor	₹ 349
Heater	₹ 749
Pressure sensor with pipe	₹ 899
Thermostat	₹ 375
Chuck nut	₹ 250
Hall sensor	₹ 895
TOP LOAD WASHING MACHINE Spin issue	Rate
Whirlpool TSP	₹ 4299
Haier 6.5kg clutch assembly	₹ 3799
Clutch assembly	₹ 3499
Damper rod Balancing rod (Four Nos.)	₹ 1499
Shocker set (four nos.)	₹ 1399
Drain motor	₹ 1349
Lid magnet switch	₹ 349
Spin timer	₹ 499

TOP LOAD WASHING MACHINE Accessories	Rate
Outer body cabinet	₹ 2490
Spin tube plastic	₹ 2190
Plastic tube	₹ 1890
Other tube	₹ 1499
Water filter	₹ 1345
Pulsater with snap	₹ 1105
Chemical wash (drum assembling & dismantling)	₹ 1016
Stand trolley	₹ 850
Lint magic filter	₹ 299
Spin led	₹ 549
Inlay panel control panel	₹ 499
Sensor pipe	₹ 175
Lid magnet switch	₹ 375
Pulsator snap	₹ 199
Agitator	₹ 849
Power plug top 3pin	₹ 199
Tap adapter	₹ 449
Motor pulley	₹ 445
Knob	₹ 99
Extension inlet pipe with adapter	₹ 590
Washing machine cover	₹ 490
Drain pipe	₹ 249
Inlet pipe (adaptor also)	₹ 449
Wiring harness repair	₹ 175
Rat mesh	₹ 299
Power cord	₹ 349
TOP LOAD WASHING MACHINE Water leakage	Rate
Drain case assembly (DV case assembly)	₹ 999
Drain case cleaning	₹ 425
Drain bellow	₹ 290

AASENAA WEATHERS (Washing Machine) RATE CARD

Descaling powder	₹ 150
Drain valve spring	₹ 99
FRONT LOAD WASHING MACHINE Power unit	Rate
Repair inverter PCB	₹ 2899
Repair PCB	₹ 2390
Timer	₹ 2190
Motor control unit MCU	₹ 1445
LVT	₹ 645
Re wiring (cut & burn)	₹ 599
Wiring kit	₹ 299 Labour
Replace new display PCB	₹ 299 Labour
Replace new PCB	₹ 299 Labour
FRONT LOAD WASHING MACHINE Wash issue	Rate
Complete drum assembly (Bosch/Siemens)	₹ 8499
Motor universal	₹ 3990
Direct drive motor	₹ 3995
DC inlet valve 3/4 way	₹ 1998
DC inlet valve 1 way	₹ 990
DC inlet valve 2 way	₹ 1432
DOOR LOCK	₹ 1299
AC inlet valve 1 way	₹ 699
AC inlet valve 3/4 way	₹ 1399
Hall sensor	₹ 1045
Thermostat	₹ 499
AC inlet valve 2 way	₹ 969
Heater	₹ 1049
Heater sensor	₹ 499
Pressure sensor with pipe	₹ 899
Drum pulley	₹ 445
Capacitor	₹ 149

V belt	₹ 845
FRONT LOAD WASHING MACHINE Spin issue	
Rate	
Shocker set 2 Nos.	₹ 1599
Drain pump motor	₹ 1599
Complete tub & drum assembly	₹ 5999
Assembly drain pump	₹ 1396
Drain pump motor (double way)	₹ 2199
FRONT LOAD WASHING MACHINE Water leakage	
Rate	
Back and front tub	₹ 2599
Front tub	₹ 1799
Drain cleaning	₹ 259
FRONT LOAD WASHING MACHINE Noise issue	
Rate	
Flange shaft tri angle	₹ 2499
Drum bearing (Oil seal with cleaning)	₹ 2349
FRONT LOAD WASHING MACHINE Accessories	
Rate	
Dispenser angle	₹ 449
Chemical wash (drum dismantling & assembling)	₹ 1499
Frontload trolley (stand)	₹ 1299
Wiring harness repair	₹ 179
Rat mesh	₹ 299
Descaling powder	₹ 165
Stand trolley	₹ 890
Door hinge	₹ 1090
Drain rubber house	₹ 699
Drain pipe	₹ 299

AASENAA WEATHERS (Washing Machine) RATE CARD

Inlet pipe 1.5 mtr with adaptor	₹ 449
Knob	₹ 99
Noise filter	₹ 499
Inlay panel control panel	₹ 549
Sensor pipe	₹ 149
Outer body (Cabinet)	₹ 2990
Tap adaptor	₹ 558
Top power plug 3pin	₹ 149
Outer body (Cabinet)	₹ 2999
Back tub (with bearing and seal)	₹ 1799
Tub drain detergent drawer house rubber pipe	₹ 549
Power cord	₹ 349
Gasket- door diaphragm	₹ 1599
Gasket spring	₹ 149
Extension inlet pipe (4mtr. With adaptor)	₹ 599
Front holder / door lever	₹ 799
Back holder	₹ 599
Washing machine cover	₹ 499
Socher pair	₹ 1399
Pulley drive	₹ 749
RF Filter	₹ 449
Outer tub	₹ 2499
door assembly	₹ 1799
FRONT LOAD WASHING MACHINE Installation	Rate
Installation / Uninstallation Labour ₹ 299	₹ 99